

Norman H. Bangerter, Governor Dee C. Hansen, Executive Director Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

November 4, 1985

TO:

File

FROM:

Rick P. Summers, Reclamation Hydrologist

RE:

Site tour of Hydrocarbon's Gilsonite Operations, Cottonwood

Mine, Black Gnat Mine, and Wild Horse Mine, DOE 047/013,

DOE 047/001, DOE 047/002, Uintah County, Utah

On August 13 and 14th, 1985, Dave Darby, Dave Cline, and myself toured the above listed operations. At the Cottonwood mine, personel were conducting operations to ready the mine for operation. The site appeared to be less than two acres in area and was generally orderly and well kept. It appeared that the pad had recently been inunduated with water, but no erosion was occuring off site.

The Wild Horse Mine is currently active and we met with Grant Green, lead miner, at the property. He indicated that they were currently 250 ft. into the mine. An old shaft to the West of the current shaft was abandoned and fenced adequately. An old sedimentation pond is located just to the East of the active shaft, but is not currently used due to the fact it was constructed directly on the vein and leaches water very rapidly into the active mine shaft. The disturbed area appeared to be very close to two acres (paced by DOGM employees). The operator should be asked to verify the extent of the disturbed area and the dates of disturbance.

The Black Gnat Mine is currently not active. The only indication of the minesite is an abandoned shaft and old timbers. No recent activity was observed at the site.

Additionally, while in the rea, the newly constructed bag and processing plant for Hydrocarbon's properties was toured. The plant was not finished and operations had not been initiated at the facility to date. The bag plant is located just east of Pelican Lake.

rps 0317R-60